

SOIL TESTING SERVICES OF WISCONSIN, INC.  
CONSULTING SOIL & FOUNDATION ENGINEERS  
540 LAMBEAU ST., GREEN BAY, WIS. 54303

PHONE: (414) 494-9656

JOHN P. GNAEDINGER, P.E.  
CLYDE N. BAKER, JR., P.E.  
WILLIAM M. PERPICH, P.E.  
WILLIAM C. KWASNY, P.E.

RECEIVED DNR

FEB 20 1976

15th Mich. Dist.

Date February 19, 1976

Harris & Associates

STS Job No. 6148 A

2718 North Meade Street

Structure Lehrer Landfill

Appleton, Wisconsin 54911

Location \_\_\_\_\_

Attention: Mr. Ted Harris

Gentlemen:

☒ herewith

We are sending \_\_\_\_\_ 3 sets of prints of

☐ under separate cover

- ☐ Boring Logs and Location Diagram
- ☐ Laboratory Compaction Data
- ☐ Field Compaction Control Data
- ☐ Classification Test Data
- ☐ Consolidation Test Data
- ☐ Triaxial Compression Test Data
- ☐ Sealed Jar Samples
- ☐ Rock Core Samples
- ☐ Caisson Reports
- ☐ Concrete Report #
- ☒ Summary of Water Level Observations

for the above job.

Remarks	cc: Department of Natural Resources	cc: Department of Natural Resources ✓
	P. O. Box 450	812 South Fisk Street
	Madison, Wisconsin 53715	Green Bay, Wisconsin 54304
	Attn: Mr. Bob Glebs	Attn: Mr. Gary Kuilibert

Yours truly,

SOIL TESTING SERVICES OF WISCONSIN, INC.

Timothy K. Dahlstrand

Registered Professional Engineer, Wisconsin

FOUNDATION BORINGS AND TESTING

INSPECTION

ENGINEERING ANALYSES AND REPORTS

LEHRER LANDFILL

SUMMARY OF WATER LEVEL OBSERVATIONS

6148-A

00750

Location	Elevation Top of PVC	Elevation Ground Surface	Elevation Bentonite Seal	Water Level After Bailing	Water Level 2-5-76	Water Level 2-10-76	Water Level 2-17-76	Water Level	Water Level	Water Level
B1	725.4	724.7	721	*	*	690.7	690.4			
B1A	726.9	725.4	688.5	Dry	689.9	692.2	693.9			
B2*	731.9	729.7	726	*	*	*	*			
B3	724.44	723.1	627	626.4	651.9	653.9	653.6			
B3A	724.2	723.0	658	655.2	693.2	694.7	696.2			
B3B	722.9	724.39	683	676.9	697.9	697.9	697.9			
B4	668.5	667.1	620	618.5	638.1	641.8	644.5			
B4A	668.6	667.1	639.5	638.6	645.3	647.1	648.8			
B5	730.2	728.9	642.5	***	682.2	683.2	683.2			
B5A	730.4	729.1	664	667.3	682.4	683.9	684.4			
B5B	730.5	729.0	683.5	680.7	724.5	724.5**	716.5			
B6	680.24	678.84	619	653.2	653.2	653.9	654.2			
B6A*	*	*	629.5	*	*	*	*			
B6B	679.24	679.24	644.5	644.8	656.9	658.2	659.7			

Notes

1. All elevations referenced to Kaukauna City Datum

2. B1 and B2 completed in July, 1974. Remaining borings completed during December, 1975 and January, 1976.

\* Unable to locate

\*\* Rebailed to 693.5 on 2-10-76

\*\*\* WL @ 693.5, 1 Hr. after bailing  
Could not bail below 682